City of Springfield Water Pollution Control Section Pollution Complaint/Report Form

	Date_10-11-0-1
	Received By: Gewe Pabst
Report From:	Received By: Gewe 14051
☐ Citizen	Referred To:
XFire Dept	Date of Incident: 10-16-07
Sewer Maintenance	
Other	
Complainant Information:	Responsible Party Information:
Name Bootman's Roy K	Name Security Armour Services Inc.
Name Boatman's Bank Address Mc Daviel & South:	Address St. Pouis Mo
Phone	Phone
Directions(if needed)	· none
Possible contamination of: [soil	groundwater ace water what body? Jordan Creek
suria	ace water what body? Toward Creek
Other Pertinent Information	From truck into Storm box. Approximate
Diesel Fuel Leal	4.0 m LANCIE TOLD ZIDIAN OOK - HABI OTIMIA IC
6-10 gallows.	
Who to contact:	
MDNR 417-883-4033	naefer
DNR 314-634-2436 CU 831-	
□EPA 913-236-3378 □ Street	
☐Fire Dept 864-1719 ☐ Health	
☐ Police Dept 864-1719 ☐ Sewer N	
Details of Incident: I received	a Dage from the Fire Dest, At Approximatel
5:30 P. m (10-16-89), requestive AS	sistance. I arrived At Approximately
5:50 P.M. I was informed that	Security Armour Services Inc. had made
A delivery to Bostman's Bank. One of	of its fuel tanks was overflowing. One of
Rootman's Security Officers asked the Armoured Car to move but they did not.	
Consciently 6-10 collars of direct went into the storm box.	
Details of Incident: I received a page from the Fire Dept. At Approximately 5:30 P.M. 10-16-89, requestive assistance. I arrived at approximately 5:50 P.M. I was informed that Security Armour Services Inc. had made a delivery to Boatman's Bank. One of its fuel tanks was overflowing. One of Boatman's Security Officers asked the Armoured Car to move but they did not. Consciently 6-10 callows of dicsel went into the stormbox. E.P.A. had received 2 Complaints about the spill. EPA. report was 18261 of 18265. Fire Marshal Kent Turner was their. He said he was sping to Constant	
18265 Fine Marchal Kent Warer WAS their. He said he was coing to Contact	
Security Armour Somires. I osted	Mr. Turner to tell Security Armour Services to
report the incident since E.P.A. ha	2 complaint
Action needed:	
DW 10-17-89 A+ 8:30 A.M.	I contacted Mr. Ed Sears about the problem
& he said he would call it in to a	Fofferson City.
No Cleany was possible	

200 E. Mc DANIEZ

Mary L. Frerking, Purchasing Officer Boatmans National Bank S.S. Station, Box 1157 Springfield, Missouri 65805

Dear Ms. Frerking:

This letter will confirm our conversation of November 30, 1984. This office received a complaint of a yellow liquid being discharged to Robberson Street north of McDaniel. Our investigation did confirm that cooling water from Boatmans National Bank was being discharged to the street.

We understand bank personnel were taking a cooling tower, located on the roof, out of service. Chemically treated cooling water and tower solids were discharged to the roof where it drained to the street.

In most cases, the discharge of treated cooling water would not be acceptable for discharge to the Springfield storm sewers or waters of the state.

This office, the Missouri Conservation Department, and the Missouri Department of Natural Resources has spent many hours in the investigation of similar water pollution incidents in the Jordan Creek Valley.

Your elimination of this discharge to the storm sewer is advised. While your contractor is repairing the cooling tower, it may be prudent to make provisions for draining the tower water and solids to the sanitary sewer.

If you have any questions, please do not hesitate to contact this office.

Yours truly,

Stephen D. Short

Water Pollution Control Inspector II

tophen D. Shot

Surveillance & Enforcement

SDS: js

cc: Henry Cole, P.E.

File (2)

200 E. Mc DANIER